ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
10

Ward Name
Dodda Bommasandra

Street ID
W0312, W0393, W0397, W0403, W0314, W0316, W0401, W

Street Name
Chikkanna Lyt 3rd Crs, NA, V S T Opposite, 3rd Crs, Chikkanna Lyt 2nd Crs, 1st Crs, Chikkanna Lyt 1s

Significant Landmark
Raja Beedi and Doddabommasandra

Segment No.
10/S-W0312/S084521

Total Length (m)
340.34

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	72.40	77.558809	13.059839	77.558698	13.059198	M0007	W0326
2	63.45	77.558559	13.059479	77.558275	13.059185	W0318	DEAD END
3	15.73	77.558175	13.059437	77.558319	13.059416	W0395	W0399
4	45.26	77.558386	13.059523	77.558486	13.059273	W0318	W0401
5	55.81	77.558217	13.059557	77.558715	13.059442	W0403	W0393
6	15.59	77.558485	13.059535	77.558504	13.059675	W0314	W0318
7	58.35	77.558232	13.059737	77.558760	13.059659	W0393	W0403
8	13.75	77.558371	13.059848	77.558493	13.059814	W0312	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Roads at Raja Beedi and Doddabommasandra in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
2400000

Sanctioned Year
2016

Year
2016 - 2017

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details
Improvements to Roads at Raja Beedi and Doddabommasandra in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
010-17-000004

Work Order No.
BBMP/EE/BTP/WO/109/2016-17

Work Order Date
19/08/2016

Period of Extention
90 DAYS

Defect Liability Period From

	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
19/08/2016	18/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00

Phone No.	E-Mail ID
9449863065	

Field Inspection Details

Number of Trees	Any Other Information	Name
1		MADHAVA RAO

Date of Inspection	Remarks
07/12/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0312, W0393, W0397, W0403,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	07/12/2016	06/01/2017	COMPLETED
SE	VASU K M	07/12/2016	06/01/2017	COMPLETED
EE	YARAPPA REDDY	07/12/2016	06/01/2017	COMPLETED
AEE	SHIVAKUMAR	07/12/2016	06/01/2017	COMPLETED
AE	MADHAV RAO	07/12/2016	06/01/2017	COMPLETED
AE	MADHAV RAO	07/12/2016	06/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0312, W0393, W0397, W0403,